

## PROJECT UPDATE

### *ADDRESS*

*MOUNT ALBERT, ON  
LOG 1M0*

### **Storm outfall locations:**

- 66 Alice Street (Rear-lot)
- 68 and 70 Alice Street (Rear-lot)
- Behind 15 and 17 Valley Mills Road (2 Storm Outfalls)

### **Retaining wall locations:**

- Behind 13 and 15 Valley Mills Road

The Town of East Gwillimbury is updating the community about the storm outfalls and retaining wall that need repair.

Town staff investigated and continue to monitor the condition of the outfalls. Although repairs are needed, the current state is stable and interim holding repairs will be completed (if necessary) until construction takes place. The slope behind 13 and 15 Valley Mills Road was also inspected, monitored, and deemed stable. This project was discussed as part of the 2022 budget deliberations at Council. The Town is continuing to make progressive steps to address this matter.

A map of the area is available on the other side of this page. It identifies the retaining wall and outfall locations. This project has several factors that are being considered as part of the repairs, including slope stability, erosion, construction access, environmental and trail impacts.

With input from external construction and engineering professionals, in February/March 2022, the Town will prepare a report which will identify and recommend potential solutions and next steps. This report will illustrate alternatives relating to the retaining wall extents and adjacent natural trail. We anticipate the detailed design to take place in 2023.

For updates on this project, please visit the Alice Street and Valley Mills Road project page at [www.eastgwillimbury.ca/alice-valleymills](http://www.eastgwillimbury.ca/alice-valleymills)

If you have any questions, please contact:

Mr. Ray Wrzala C.Tech.  
Senior Engineering Technologist  
[rwrzala@eastgwillimbury.ca](mailto:rwrzala@eastgwillimbury.ca)  
905-478-4282 ext. 3852

